

Intertek The Warehouse Brewery Lane Leigh WN7 2RJ UK Tel +44 1942 265 700 consumergoods.uk@intertek.com intertek.com

## FLAMMABILITY TEST REPORT

| Report No.: LEI19080837A  | Date Received: 06/08/19   | Date Tested: 12/08/19        | Date Issued: 12/08/19 |
|---------------------------|---|------------------------------|-----------------------|
| Company Name & Address:   | FARGOTEX SP. Z O.O.<br>AL. LEGIONÓW 114 C<br>18-400 ŁOMŻA<br>POLSKA |                              |                       |
| Contact Name:             | EWELINA SŁABY   |                              |                       |
| Sample Details:           |   |                              |                       |
| Reference No.:            | Not stated  |                              |                       |
| Order No.:                | Not stated  |                              |                       |
| Style No.: / Batch No.:   | Milton New  |                              |                       |
| Quality:                  | Knitted   |                              |                       |
| Fabric Colour:            | Not stated  |                              |                       |
| Manufacturer:             | Not stated  |                              |                       |
| Supplier:                 | Not stated  |                              |                       |
| Buyer / Retailer:         | Fargotex  |                              |                       |
| Intended Use:             | Furniture Fabrics   |                              |                       |
| Quoted Fibre Composition: | 97% Polyester, 3% Nylor   | n                            |                       |
| Retailer:                 | Not stated  |                              |                       |
| Specification No.:        | Not stated  |                              |                       |
| Sample Description:       | Blue coloured woven fab   | ric with white coloured wove | n backing             |

| Test Method   | Pre Treatment | Requirement   | Result   |  |
|---|---------------|---|----------|--|
| BS 5852: Part 1: 1979,<br>Ignition source 0<br>(Cigarette)  | None          | Compliance with Schedule 4 Part 1<br>(The cigarette test) of The Furniture<br>and Furnishings (fire) (safety)<br>Regulations 1988 (as amended). | Complies |  |
| <b>Note:</b> Fabric was submitted for test rather than the upholstery composite so as suggested by The Guide to the Furniture Regulations the cover fabric was tested for cigarette resistance using standard polyurethane foam (non- |               |   |          |  |
| modified) as this will give the furniture manufacturer a good indication of its likelihood to pass the cigarette test for the finished article  |               |   |          |  |

STEVEN OWEN (Technical & Operational Excellence Manager)

Report No.: LEI19080837A Page 1 of 2

. . . . . . .

ANDREW HALLETT (Flammability Team Leader) CAROLE SPOWART (Flammability Administrator)









Intertek The Warehouse Brewery Lane Leigh WN7 2RJ UK Tel +44 1942 265 700 consumergoods.uk@intertek.com intertek.com

## FLAMMABILITY TEST REPORT

| <u>Test Specification</u><br>Test Method: | BS 5852: Part 1: 1979 as modified by Schedule 4 Part 1 of the Furniture and   |
|---|---|
|   | Furnishings (fire) (safety) Regulations 1988 (as amended).  |
| Ignition Source:                          | Filterless cigarette  |
| Side Tested:                              | Face  |
|   |   |
| Filling Specification                     | Detrustions from  |
| Filling Type:                             | Polyurethane foam   |
| Supplier / Grade:<br>Size:                | Carpenter / RP21130 Unmodified  |
|   | 450 X 300 X 75mm (back) & 450 X 150 X 75mm (seat)   |
| Density / Hardness:                       | 20-22 kg/m <sup>3</sup> / Type B, 130N  |
| Pre-treatment / Durabilit                 | v procedure   |
| None                                      | <u>, procedure</u>  |
| None                                      |   |
| Conditioning                              |   |
| <u>Conditioning</u>                       | At least 72 hours in ambient indeer conditions, then at least 16 hours in an  |
| Prior to testing:                         | At least 72 hours in ambient indoor conditions, then at least 16 hours in an atmosphere having a temperature of $20\pm5^{\circ}$ C and a relative humidity of $50\pm20\%$ |
| At Time of Testing:                       | Temperature between 15°C & 30°C. Relative humidity between 20% & 70%  |

## **Test Results**

"The following test results relate only to the ignitability of the combinations of materials under the particular conditions of test: they are not intended as a means of assessing the full potential fire hazard of the materials in use."

| conditions of iesi, they are not intended as a means of assessing the full potential fire hazard of the materials in use. |  |  |
|---|--|--|
| Ignition source 0 (Test 1):   | The cigarette burnt out within 23 minutes, there was no flaming or progressive |  |
|   | smouldering. (Pass)  |  |
| Ignition source 0 (Test 2):   | The cigarette burnt out within 24 minutes, there was no flaming or progressive |  |
|   | smouldering. (Pass)  |  |

## **Conclusion**

The composite tested meets the requirements of Schedule 4 Part 1 (The cigarette test) of The Furniture and Furnishings (fire) (safety) Regulations 1988 (as amended). **PASS.** 

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have <u>aimed</u> to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or willful misconduct.

Report No.: LEI19080837A Page 2 of 2



